

CCWD Monthly Leak Report - March 2019

	Date Reported Discovered	Date Repaired	Location	Pipe Class	Pipe Size & Type	Estimated Water Loss MG
1	3/13/2019	3/18/19	106 Navarra Ave.	Service	3/4" Copper	0.003
2	3/21/2019	3/21/2019	383 El Granada Blvd	Service	1" Copper	0.002
3						
4						
5						
6						
7						
8						
Total						0.005

OTHER DISCHARGES

Total Volumes (MG)

Flushing Program	0.010
Reservoir Cleaning	0.000
Automatic Blowoffs	0.117
Dewatering Operations	0.000
Other	0.023

PLANNED DISCHARGES

GRAND TOTAL (MG)

0.150