

MONTHLY REPORT

To: Mary Rogren, General Manager

From: Sean Donovan, Water Treatment Operations Manager
Darin Sturdivan, Water Distribution Operations Manager
Todd Schmidt, Water Treatment Supervisor
Dustin Jahns, Distribution Supervisor

Agenda: January 13, 2026

Report

Date: January 9, 2026

Monthly Highlights

- Replaced failed PLC module at Denniston.
- Continued prep/painting of outdoor piping at DWTP.
- Updated Hach WIMS database.
- Crystal Springs Pump Station annual fire inspection.
- Main St PRV rebuilt and serviced.
- Annual PRV inspections.
- Replaced Alves Pump 2 Motor.
- Fire hydrant maintenance.
- GSW has mobilized and completed test borings for well project. Well drilling will begin late January early February.
- El Granada Tank 3 Site - stand-by generator positioned while repairs are made to primary generator.
- Pilarcitos Canyon - commenced tree work to clear downed trees from Christmas storm.

December Sources: Pilarcitos Reservoir, Denniston Creek, Pilarcitos Wells.

Main leaks/service leaks: None.

Hydrants replaced:

- 50 Pembroke Ct.
- 18 Pinehurst Ln.

Projects

- EKI Environment and Water, Inc.
 - Provided peer review of DN Tank project coordination/engineering.
 - Submittal review and tracking of Well Project.
 - Provided construction support for Pilarcitos Wells Project.

STAFF REPORT

Agenda: January 13, 2026

Subject: Operations Report

Page 2

- Continued work on environmental permitting requirements for Pilarcitos Culvert Repair and Pilarcitos Slide Repair Project.

- HDR, Inc.
 - HDR continued work on DN Tank submittals and plan modifications and coordination of subcontractors.