

MONTHLY REPORT

To: Mary Rogren, General Manager

From: Sean Donovan, Water Treatment Operations Manager
Darin Sturdivan, Water Distribution Operations Manager
Todd Schmidt, Water Treatment Supervisor
Dustin Jahns, Distribution Supervisor

Agenda: March 10, 2026

Report

Date: March 6, 2026

Monthly Highlights

- Pilarcitos Wellfield Replacement Project: GSW Construction/ Gregs Drilling were on site during the month. All wells have been drilled and well development is starting.
- Updated Hach WIMS Production database.
- Conducted LT2 (Long Term 2 Enhanced Surface Water Treatment Rule) sampling.
- Replaced pump and motor at El Granada Tank 3 site.
- Conducted fire hydrant maintenance.
- Finished labeling outdoor piping at Denniston WTP.
- Denniston WTP was offline for six days due to weather.
- Maintenance Worker, Jose Macias Gonzalez passed his D2 exam.
- Operator Carson Anderson passed his D3 exam.

Services installed

- 139 Valencia Ave., Fire
- 200 Columbus, Fire & Domestic

Sources: Pilarcitos Reservoir, Denniston Creek, Pilarcitos Wells.

Main leaks/service leaks: None.

Hydrants replaced:

- 287 San Carlos Ave.

Projects

- EKI Environment and Water, Inc.
 - Provided peer review of DN Tank project coordination/engineering.
 - Conducted submittal review and tracking of Pilarcitos Wellfield Replacement Project.
 - Provided construction support for Pilarcitos Wellfield Replacement Project.

STAFF REPORT

Agenda: March 10, 2026

Subject: Operations Report

Page 2

- Continued work on environmental permitting requirements for Pilarcitos Culvert Repair and Pilarcitos Slide Repair Project.

- HDR, Inc.
 - Continued work on DN Tank submittals and plan modifications and coordination of subcontractors.